

Please adjust the spindle pitch in both axes to 14,15mm and the motor current to 0,7A and store it into the controller. This should solve the issue.

